


# Technical Service Bulletin

## Drill Hole Pattern for The Model 66, 70 & 80 Standard Housing Actuators


August 1, 2005



- Requires 3 - 1/2" x 4" Grade 5 bolts w/lock washers (not included)
- All TIE DOWN ENGINEERING standard actuators have the same hole pattern for consistent tongue hole placement

Instruction Sheet #08074

**TIE DOWN ENGINEERING • 5901 Wheaton Drive • Atlanta GA, 30336**  
**www.tiedown.com • (404) 344-0000 • FAX (404) 349-0401**



081105,C809